

Page: 1of 9

Inspection Report

Client Name

.

Commodity & Quantity

: Pneumatic Rubber Fender: (DIAMETER:1.5M,LENGTH:3.0M):4PCS Pneumatic Rubber Fender: (DIAMETER:3.3M,LENGTH:6.5M):15PCS

Inspection date

: October 25,2017

Inspection Location

.

Scope of Inspection

: 1. Packing and Marking

2. Size checking (the overall L & D)

3. Overall visual inspection

Charge pressure witness (50KP)

INSPECTION PERFORMED

Storage Condition:

At the time of our attendance at the factory, we found the fenders stored in the manufacturer's open yard in normal condition.

Sample plan:

According to the client's request and ISO 17357-2014, general inspection level II, total 2pcs (D: 1.5M, L:3.0M) and 4pcs(D:3.3M,L:6.5M) of fender were randomly selected for inspection.

Packing:

The Fenders were in nude packing.

Marking:

The size and serious No. were painted on the body of fender.

Charge pressure witness (50KP):

Per client requirement, the above mentioned 6pcs fenders were charged pressure 50KP under BV inspector witness for about half a hour. They were in normal on site.

The pressure gage was provided by supplier without calibration certificate, the result was for reference only.

Overall visual inspection:

From the selected 6pcs of fenders, BV inspector found the fenders in normal condition without obviously damage and scratches.





BV Ref.:

GTS 2017 298634

Page:

2of 9

Size checking:

The above mentioned 6pcs of fenders were measured by us, including the length and diameter, details as below:

The measurement was done by supplier as not direct measurement, and the data as under were for reference only.


Size:1.5M*3.0M			
Sample No.	Diameter(M)	Length(M)	
16	1.51	3.13	
17	1.56	3.05	

Size:3.3M*6.5M			
Sample No.	Diameter(M)	Length(M)	
. 1	3.35	6.42	
3	3.25	6.53	
13	3.32	6.48	
14	3.41	6.61	

Photo Report Storage condition













Page:











Marking







Page:

4of 9

Size checking 1.5M X3.0M















Page:










Size checking 3.3M X6.5M







Page:















BV Ref.: GTS

GTS 2017 298634

Page:









Overall visual inspection 1.5M*3.0M







Page:









Overall visual inspection 3.3M*6.5M







Page:









Kevin Tang

Bureau Veritas Bivac Asian CRE (Shanghai) Inspection Co., Ltd.



